

**TOWNSHIP OF NORTH HUNTINGDON
WESTMORELAND COUNTY, PENNSYLVANIA
DEPARTMENT OF PUBLIC WORKS**

**RICHARD G. ALBERT, DIRECTOR OF PUBLIC WORKS
TAB N. FYOCK, ASST. DIRECTOR OF PUBLIC WORKS**

May 2022

ROSE ST:

Part of the Township drainage system that was failing causing unsafe condition.

- Saw cut and excavation
- Replaced 150' of 15" pipe
- Replaced 24' of 12" pipe
- Re-constructed 2 inlets
- Resurface area

WHITEHEAD LN:

Part of the Township drainage system that was failing causing unsafe conditions.

- Saw cut and excavation
- Replaced 100' of 18" pipe
- Re-construction of 1 inlet
- Resurfaced all areas

ORMSBY DR:

Part of the Township drainage system failing causing unsafe conditions.

- Saw cut and excavation
- Replaced 80' of 24" pipe
- Re-constructed 2 inlets
- Resurfaced all areas

INLET REPAIR:

Part of the Township drainage system that was failing causing unsafe conditions.

- Harvie Ct, Re-Constructed box, resurfaces all area
- Mike Rd, Installed 6" discharge

MACK RD:

Large section of road failing causing unsafe condition.

- Saw cut and excavation
- Sub-base installed
- Re-surfaced area

MISCELLANEOUS WORK

- Water St: Cleaned out storm intake
- Hilltop Rd: repairs to outfall
- Storm cleanup, misc locations

SIGN DEPARTMENT:

- The Sign Department continues their regular duties of installation of road signs based on legal criteria. They also have the duties of marking the PA One Calles and tracking permitting and inspection of road openings.

STREET SWEEPER UPDATE:

- Back in service and in uses.

MOWER:

- The mower is out when able.

EMERGENCY CALL IN:

- 5/5/22 Trees
- 5/6/22 Flooding

If you have any questions concerning this report, please feel free to contact me.

Richard Albert

Richard G. Albert
Director of Public Works